Approved For Belease 2002/10/24. RDP99B00048R000100010006-1

R	36
	25X1/

USAFE SUPPORT AT

20 July 1964

	_	٠,	4		
,	5	Х	1	Α	

25X1A

1. Support supplied by USAFE to during March, April, May and part of June 1964 consisted of personnel, equipment and services. The personnel group enlisted men. The equipment was of the type was one officer, necessary to support a flying operation at a remote site, fire truck, generators, fuel truck, mobile radio navigation aid, mess hall gear and some recreational equipment. Services provided was the operation and maintenance of the equipment and house keeping functions such as operating a scheduled movie, a BX facility, managing the BOQ and operating the mess hall.

- 2. The support outlined above was subject to some criticism.
- a. The equipment was drawn from stored USAFE assets and airlifted to the operating location. The complaints in this area were focused on the fuel truck, the fire truck, and the 100 KVA generator and the kitchen wan. The fuel truck filters were almost unserviceable and some of the seals were deterior a bed to the point that severe leakage occured. The tractor was satisfactory. The 0-11 fire truck had some components which had not been maintained and the truck needed a general tune up and inspection. The 100 KVA generator was shipped with a bad starter system and consequently, was never used. It appeared to be serviceable otherwise. The kitchen was was shipped with some components missing. The cooking utensils and field repair kits for the stoves were missing. Utensils were locally purchased, but the best quality available was minimum satisfactory for use on the field stoves. Stove repair was accomplished by camabilization. These complaints could have been prevented by an inspection of the equipment before shipment.

25X1A

provided by the 2nd Mobile Communications Squadron, USAFE b. The mobile was in good condition and operated satisfactorily. At one time it was the only usable ground mavigation aid available within 150 miles.

	Approved For Belease 2002/19/31 CIA-RDP99B00048R000100010006-1						
	c. The personnel support provided was excellent. many times was 25X1	Α					
	faced with problems with which he had no experience. He utilized every means						
	available to get the utmost out of the limited and faulty equipment he had to						
1A	work with. His supported him and the effort to the best of their ability.						
	They all worked at what ever was needed to get the job done. The firemen oper-						
	ated and maintained the movie projector. The operator managed the BX fac- 25X1	Α					
	ility, the desiel mechanic kept the kitchen refrigerators and all other motor-						
	ized equipment going. The two mess supervisors had very limited local help so						
	they did the cooking, kept the stoves in working order, served the food and main-						
	twimed the best possible degree of kitchen samitation.						
	d. The food provided was also subject to many complaints. The distance from						
	supply point to user dictated the type of food available. This can be improved						
	only by getting food from a nearer supply point.						
	3. The following recommendation is offered to alleviate some difficulties in						
	supporting operations						
	a. In spite of the assigned area of support responsibility it appears that						
	support would be more economical and far better if futuredetachments at 25X1	Α					
	were supplied and supported from PACAF assets. The distance involved with						
١	USAFE support creates monumental logistics problems which require expensive and						